

*United States Coast Guard
Activities Baltimore
Coast Guard Activities Baltimore
Investigations / Intelligence Branch*

2401 Hawkins Point Road Bldg # 70

Baltimore, MD 21226

Phone: (410) 576-2558

Fax: (410) 576-2583

FAX COVER SHEET

From: LT. Scott Baranowski

To: Tom Roth-Roffy

Fax: 202-314-6454

Date: 27 August 2004

Re: LADY D stability information. The first two pages are in reference to the weighing of the vessel. The rest of the pages were utilized to assist in determining the canopy weight. Please let me know if you have any questions.

PLEASE NOTE THIS COMMUNICATION MAY CONTAIN CONFIDENTIAL INFORMATION THAT IS INTENDED ONLY FOR THE INDIVIDUAL OR ENTITY NAMED AS THE RECIPIENT. ANYONE OTHER THAN THE RECIPIENT OR THE INTENDED RECIPIENT'S AGENT OR EMPLOYEE IS PROHIBITED FROM READING, DISSEMINATING, COPYING OR DISTRIBUTING THE INFORMATION CONTAINED IN THIS FACSIMILE TRANSMISSION. IF THIS TRANSMISSION HAS BEEN RECEIVED IN ERROR, PLEASE NOTIFY THE SENDER IMMEDIATELY AND RETURN ALL MATERIALS TRANSMITTED ERRONEOUSLY.

9 PAGES INCLUDING COVER SHEET

EDGEMERE TERMINALS, INC.

8004 Stansbury Road
Baltimore, Maryland 21222
Phone: (410) 282-4420

CAUSA
CORPORATION

CUSTOMER'S NAME _____

CARRIER _____

INBOUND 08-11-2004

OUTBOUND 08-11-2004

7040

10420

DRIVER ON _____ OFF _____

SHIPPER _____

WEIGHER _____

Certified by Maryland Dept. of Agriculture Control # 15493

on board Br w/ estimate

~~per bench~~

anchor

bow ladder

console + seat

Hand a 90 Hp


— Battery

2 fuel tanks (empty)

tarps

10# dry chum fire extinguisher

Bill Bench Port



shelf = 1x4x1x8
seat 1x8 (2)


22' all present

spring off support = 44" oc

Br. all the way round $1\frac{1}{4} \times 1\frac{1}{2} \times \frac{1}{16}$

Aft window/panel

haft of
steel bench




Aft door (29")

3x3 skin panel

+ fire ext bracket

other Back Panel

missing sliding window
fixed is present



2x4 rubrail 21' missing (steel)

40"

Thin gauge steel \Rightarrow no insulation

front shear - same



Back door - same

no shelf

Bench & shelf (std) under seat
— see pic

Fuel tanks —




Same windows — diff #




1/4 square channel Al
" 1/16 in ?

maybe all same

Side



92
-62
30
24




$$\begin{array}{r} 98 \\ +26 \\ \hline 79 \end{array}$$

$$\begin{array}{r} 81 \\ 92 \\ 74 \\ \hline 18 \end{array}$$

○ Maybe a base payment too

no windows




1 1/4" thick

96" 1/8 b 7B


16 1/2" ab


8'-6" from
ab to top
super

no front
work





all measured
to rail
deck
5'-1"





missing 2' of wall

2' of channel / angle



9" in port tank F/O - water

12 1/2" steel tank